To: Hoppe, Michael[Hoppe.Michael@epa.gov]

Cc: Amy Picunas[PicunasAE@cdmsmith.com]; Vaughn, Stephanie[Vaughn.Stephanie@epa.gov]

From: Stan Kaczmarek

Sent: Wed 8/21/2013 1:49:14 PM
Subject: Re: Air monitor and Info Sheets

The repairs have been made. Stan Kaczmarek, PE de maximis, inc. 186 Center Street, Suite 290 Clinton, NJ 08809 (O) (908) 735-9315 (C) (973) 978-9621

>>> On 8/20/2013 at 12:25 PM, in message <e5ef7a913ea742f9a034dd2d94ee5160@BY2PR09MB062.namprd09.prod.outlook.com>, "Hoppe, Michael" <Hoppe.Michael@epa.gov> wrote:

Stan,

Please have the monitoring crew repair/replace the sampling port on the mobile location particulate monitor. See photo. It is missing a spacer and therefore the top cap/lid is covering 1/3 of the inlet itself, biasing the results low.

Also, the location is behind a large tree and should be reconsidered.

Lastly, the packet of information pamphlets was empty and I replenished the supply from the near water location. Please have the crews check and replenish the boxes daily.

Not major items, but easily fixable.

Thank you.

Mike